



26 February 2020



Dear 

**Response to official information request for current/existing fault log for Moonshine Road (culverts, road surface and vegetation)**

I refer to your request for official information received 3 February 2020 relating to current/existing fault log for Moonshine Road (culverts, road surface and vegetation). We have processed your request under the Local Government Official Information and Meetings Act (LGOIMA) 1987.

The information you requested is outlined below.

This fault log will be used to help the Council prioritise Moonshine Road fault repairs alongside others identified across Porirua's rural network as part of a wider programme of work.

Moonshine Road fault log	
Location	Description
1089	Culvert needs outlet clearing and jetting
1222	High grass shoulder needs cutting back
1281	Road. Edge needs building up with basecourse and dealing
1399	Culvert marker post broken needs replacing
1201	Dig out repair
1192	Dig out repair
1183	Dig out repair
1175	Dig out repair
1960	Culvert marker post needs culvert number
2037	Culvert marker post missing
1958	High shoulder needs cutting back
2166	Culvert marker post has no number
2376	When watertables have been established edgebreaks should be done
2377	Edgebreak repair and shoulder should be built up with basecourse and sealed
2447	Number missing off culvert marker post
2509	Culvert marker post number missing
2444	High shoulder needs cutting back
2791	Dig out repair
2833	Dig out repair
3457	Culvert marker post number missing
3590	Culvert marker post number missing
3541	Major dig out road badly shunting and pot holing
3206	Culvert marker post number missing
3179	Culvert marker post number missing

## Moonshine Road fault log

Location	Description
3015	Culvert inlet is sitting too high requires lowering and culvert marker post number is missing
2969	Culvert blocked water running over the top of grid may need jetting, and culvert marker post number is missing
2866	CMP broken needs replacing
45	Edgebreak repair
279	Water table needs clearing and reshaping
1469	Culvert inlet requires a headwall
1329	Water table needs clearing and reshaping
1527	Culvert inlet. needs a headwall
1530	Dig out repair
828	High shoulders need cutting back
1666	High shoulder needs cutting back
1840	Culvert is just a broken pipe which needs to be made bigger with a headwall
2433	High shoulder needs cutting back
3144	Slips and bank fretting need clearing out of water table
3125	Edgebreak needs repairing once the water table has been cleared
3481	Slips and bank fretting need clearing out of water table
3914	Asphalt on bridge deck needs renewing and the wire mesh under the asphalt needs replacing with a chip seal to make it easier for future repairs.
	Barriers on the bridge need cleaning and repainting

If you wish to discuss this further, please feel free to contact Claire Giblin, Customer Liaison Manager on telephone: 04 237 1414 or email: [claire.giblin@porirua.govt.nz](mailto:claire.giblin@porirua.govt.nz).

Ngā mihi



Wendy Walker  
**Chief Executive**  
**Kaiwhakahaere Matua**